

Structure 31 – C2005 over Lamoille River

Photos by Kristen Leahy, Zoning and Floodplain Administrator on March 20, 2024

Front view from East Main Street in Hardwick, VT



View of Bridge on right side – close to the intersection of Stannard Brook (left) View of the water course intersection with post flooding gravel accumulation (right).



Most impacted abutment on the right of the bridge.



View of Bridge on left side – closer proximity to the neighboring houses



Left view of abutment that is compromised.



View of abutment that is more compromised – note that the stone has completely broken in the center



View of less compromised abutment (Note that the abutment is also breaking in the center).



View of neighboring properties.

